


FIG. 1



F I G . 2




FIG. 3






FIG. 4



09731973-120800

F I G . 5


$L^* = 90$



09731973 120300

F I G . 6


$L^* = 85$



003021" E26FE/60

FIG. 7


$L^* = 80$



09731973-120800

FIG. 8


$L^*=75$



008021" E/6TE/60

FIG. 9


$L^* = 70$



003021" E26TE260

F I G . 10


$L^* = 65$



09/319/3 120800

F I G . 11


$L^* = 60$



008021" E/6FE/60

F I G . 12


$L^* = 55$



09731973 120800

F I G . 13


$L^* = 50$



09731973-120800

F I G . 14


$L^* = 45$



008021" E/6FE/60

F I G . 15


$L^* = 40$



09731973 120800

F I G . 16


$L^* = 35$



003027 8467260

F I G . 17


$L^* = 30$



008021 167560

F I G . 18


$L^* = 25$



008021" E/57E/60

F I G . 19


$L^* = 20$



0973197-120800

F I G . 20


$L^* = 15$



008021" E/67E/50

F I G . 21


$L^* = 10$



09731973-120800


F I G . 22

$L^* = 5$



003021" E26TE260

F I G . 23A



F I G . 23B

R	G	R	G
G	R	G	R
B	G	B	G
G	B	G	B
R	G	R	G
G	R	G	R

F I G . 23C

Ye	Cy	Ye	Cy
Mg	G	Mg	G
Cy	Ye	Cy	Ye
Mg	G	Mg	G
Ye	Cy	Ye	Cy
Mg	G	Mg	G
Cy	Ye	Cy	Ye
Mg	G	Mg	G

F I G . 23D

	R		G		B		
	G		B		R		G
		R		G		B	
	G		B		R		G
		R		G		B	

008027 "C" 67E760